P-1

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W0641, W0330, W0629, W0627, W0727, W0376, W0741, W	2nd Crs, NA, 1st Crs, 7th Crs Lakshmi Sagar Lyt, 3rd Main Rd, 2nd Main Rd, 4th Crs Kanaka Lyt, Dodd	SFS 208, SFS 407 SFS 707, Muneshwaranagara, CHS 70
Segment No.	**Total Length (m)**	
3/C-W0641/S103955	212.52	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	85.91	77.563858	13.101069	77.563627	13.100326	WO 270	END
2	126.61	77.564544	13.101069	77.564162	13.099987	WO 369	WO 270

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
1) Improvements of drains and resurfacing to roads in SFS 208 area in ward No:03, 2) Improvements of drains and resurfacing to roads in SFS 407 area i	75000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1) Improvements of drains and resurfacing to roads in SFS 208 area in ward No:03, 2) Improvements of drains and resurfacing to roads in SFS 407 area in ward No:03, 3) 2) Improvements of drains and resurfacing to roads in SFS 707 area in ward No:03, 4) Improvements of drains and resurfacing to roads	003-18-000044, 003-18-000045, 003-18-000046, 003-1
Work Order No.	**Work Order Date**	**Period of Extention**
EE/P-YNK/WO/193/2017-18	23/03/2018	EOT NOT TAKEN
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
23/03/2018	22/03/2019	No

Contractor Details

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0641, W0330, W0629, W0627, W0727, W

3/5-W0420/S012104

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
MUMESH (SMLP CONSTRUCTIONS & ASPHALT)		0.00
Phone No.	**E-Mail ID**	
9886213563		

Field Inspection Details

Number of Trees	Any Other Information	Name
200		pavana nagathi
Date of Inspection	**Remarks**	
06/08/2018		

Category	Image	Photo Remark
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0641, W0330, W0629, W0627, W

Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0641, W0330, W0629, W0627, W0727, W

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

P-1

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
3

Ward Name
Atturu

Street ID
W0400, W0729, W0382, W0376, W0276, W0222, W0369, W

Street Name
NA, Doddamuniswammppa Lyt, 1st Crs, 7th Crs Lakshmi Sagar Lyt, 2nd Crs, 2nd A Crs, Maheshwari Nagar,

Significant Landmark
SFS 208, SFS 407, SFS 707, Industrial area , CHS 7

Segment No.
3/S-W0400/S012104

Total Length (m)
3379.38

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	357.10	77.581875	13.106206	77.580355	13.103380	WO741	WO 750
2	106.22	77.576135	13.105352	77.576025	13.104398	WO745	END
3	89.67	77.575302	13.105473	77.575167	13.104673	WO727	END
4	92.49	77.574546	13.105582	77.574420	13.104755	WO 729	END
5	436.10	77.573047	13.104838	77.576993	13.104320	WO 400	WO 747
6	10.73	77.574203	13.104738	77.574301	13.104724	WO 400	END
7	120.42	77.571805	13.105374	77.572916	13.105351	WO 369	END
8	139.30	77.572519	13.105306	77.572477	13.104047	WO 375	END
9	123.94	77.573111	13.103907	77.573191	13.102789	WO 367	END
10	151.83	77.571647	13.104043	77.571679	13.102671	WO 248	END
11	103.76	77.569949	13.101492	77.570905	13.101524	WO 256	END
12	31.51	77.571376	13.101478	77.571665	13.101451	WO 265	END
13	166.06	77.571773	13.101433	77.573130	13.101923	WO391	END
14	197.78	77.570936	13.102511	77.570969	13.100724	WO 421	END
15	218.08	77.570592	13.102519	77.570624	13.100548	WO 431	END
16	307.24	77.573467	13.099710	77.576056	13.099575	WO 447	END
17	727.15	77.572632	13.098561	77.572648	13.098984	WO 501	END

Work Details

History of Road / Lane / Circles

Name of the Work
1) Improvements of drains and resurfacing to roads in SFS 208 area in ward No:03, 2) Improvements of drains and resurfacing to roads in SFS 407 area i

Sanctioned Estimated Amount (Rs.)
75000000

Sanctioned Year
2017-18

Year
2017 - 2018

Type of Work
Others

Other Work Type

Tender	Work Details	Job No. / Work Code
Under	1) Improvements of drains and resurfacing to roads in SFS 208 area in ward No:03, 2) Improvements of drains and resurfacing to roads in SFS 407 area in ward No:03, 3) 2) Improvements of drains and resurfacing to roads in SFS 707 area in ward No:03, 4) Improvements of drains and resurfacing to roads	003-18-000044, 003-18-000045, 003-18-000046, 003-1

Work Order No.	Work Order Date	Period of Extention
EE(PORJECT)/YNKZ/WO/193/17-18	23/03/2018	UNDER LIMIT

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
23/03/2018	22/03/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B.B.UMESHA (SMLP CONSTRUCTIONS AND ASPHALTS)		0.00

Phone No.	E-Mail ID
9886213563	

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0400, W0729, W0382, W0376, W

Field Inspection Details

Number of Trees	Any Other Information	Name
65		pavana nagathi
Date of Inspection	**Remarks**	
06/08/2018		

Category	Image	Photo Remark
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0400, W0729, W0382, W0376,

Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	R L Parameshwaraiah	18/09/2019	25/01/2019	Approved
SE	BASAVARAJ R KABADE	04/01/2019	25/01/2019	FORWARDED
EE	Herappa Reddy	04/01/2019	25/01/2019	Forwarded
AEE	KIRAN	27/12/2018	05/09/2018	COMPLETED
AE	PAVANA NAGATHI	06/08/2018	05/09/2018	PHOTOS UPLOADED
AE	Pavana Nagathi	06/08/2018	05/09/2018	create

AE

AEE

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0641, W0330, W0629, W0627,